

STAGE 45 ADDENDUM


Your stage 45 parts pack comes with improved replacements for two of the parts supplied in stage 2. This addendum sheet shows how to fit the new parts before you move on to stage 46.

DISASSEMBLING THE NACELLE


STEP

A

Take the nacelle assembly you began in stage 2. Remove the eight AM screws in order to detach the nacelle upper (O2D) from the nacelle upper frame (O2H).



Next, remove the three BM screws to detach the upper nacelle front (O2B), the Bussard EM field projector (O2C), and the Bussard EM field projector reflector (O2J). Now turn the page.





REASSEMBLING THE NACELLE

STEP


B

Swap the Bussard EM field projector fitted in stage 2 (02C) for the replacement projector (45K). Then replace the Bussard EM field projector reflector (02J) on top of the new piece.




Then use three BM screws to resecure the assembly to the nacelle upper frame (02H).


Replace the blue formation light (02I) from the nacelle upper (02D) with the red formation light (45L).



Finally, reattach the nacelle upper (02D) to the frame (02H) with eight AM screws.



PARTS



45K

Replacement projector
(quantity: 1)



45L

Red formation light
(quantity: 1)

STEEN009MI

